

In the case of a cone clutch, it is sometimes found that even though the leather be in fine condition and the spring adjustments right, that the clutch still grabs. A way in which this might be remedied is to collect a number of the thin corks found in bottle caps, and pry up the leather about every thirty degrees and insert these corks. Many clutches have cork

**Randolph 409.**